

Operations Report – Clearwater Operations – February 2025

02/18/25 Communications with Kenneth regarding well 1 fail alarm. Shoveled snow at well panel. Repaired leak on chlorine injection tubing.

02/21/2025 Received communications loss alarm for mid tank. Remote monitoring. Went to spring house. Reset tripped breakers. Call with Kenneth.

02/25/2025 Purchased spray in insulation. Sprayed into holes in pump house and cracks around door. Reset mid tank communications. Dug out splice box and tried to reset CB4 breaker. Calls with Kenneth and Kevin. Returned later to respond to additional alarms. Picked up generator and power cord. Set up bypass power at mid level tank. Pulled transducer and recalibrated. Observed operation.

02/26/2025 Phone calls with Kevin and Chip. Purchased irrigation cap and extension cord. Set up temporary power supply with extension cord from nearest house to tank in order to power mid tank communications. Measured tank level and calibrated with Automation Werx. Primed boosters and pumped water up to upper tanks.

02/27/25 Picked up spare chlorine pump. Call with Kenneth. CB4 Fuse was preventing chlorine injection pump from running. Disconnected wire that was shorting out CB4 fuse. Got chlorine pump outlet working again. Found and repaired leak on chlorine injection tubing.